9/28/81

C/04 GLA_ S

AND 2 SLIPS

INE FOR WET: (P.)

NE FOR DRY: (Q.)

VAL CUSHING

	(A) C/04 LEADLESS — TRANSPARENT-GLASSY FRITTED.	(B) C/04 TO C/03 ROB FORBES: MATT OLD FORMULA W/Na_2CO_3	(C) C/04 TO C/03 ROB FORBES: MATT NEW FORMULA W/(FRIT 3247.	(D) C/04 GLOSSY · BORON TYPE LEADLESS. RAW MATERIALS.	(E) C/04 MATOLICA OPAQUE · WHITE ADD 6% MASON'S GOLDEN BROWN STAIN FOR SOFTER WHITE.	(1) MATOLICA FORMULA FOR C/04 OVERGLAZES APPLY OVER BASE GLAZE	(2) (1) IS FOR SOFT, WATERY BLURRY EDGES - (2) IS FOR A HARDER MORE INTENSE COLOR.	(G)	(H) C/04 GLOSSY/TR. VERY HIGH BORON. SLIGHT BLUISH CAST.	(I) C/04 WATER BLUE BASE IS GLASSY-TRANS. ADD 1% $CuCO_3$ → BLUE.	(J) C/04 GLOSSY/TRANS. ANOTHER HIGH BORON BUT LESS BLUE THAN (H).	(K) C/04 GLOSSY/TRANS · SAFE LEAD GLAZE - TESTED. .5 PTS./MILLIMU	(L) C/04 SATIN MATT HIGH CLAY W/SOME BARIUM.	(M) C/04 SATIN MATT $H_2O \cdot CaO \cdot SiO_2$ TYPE.	(N) C/04 SATIN MATT $H_2O \cdot CaO$ TYPE.	(O) C/04 SMOOTH MATT BARIUM/ALUMINA TYPE.	(P.) C/04 WHITE SLIP WET TO LEATHER.	(Q.) C/04 WHITE SLIP DRY TO BISQUE ABSU.	(R.)
ERRO FRITT · 3124	35				40		50%			[redacted]				45	60	35	30	30	
ERRO FRITT · 3110	25									76.3						35			
ERRO FRITT · 3247			36																
IEPHELIVE SYENITE	10											20		10		10			
USTER FELDSPAR				33					35		33								
CONA F/4 SPAR		46	34		14														
ERSTLEY BORATE	2	12	12	20		75%			50	5.7	23	26		10			2		
WHITING		13	13								1		10	5					
ITHIUM CARBONATE	6			3									10						
BARIUM CARBONATE		13		5							6		6			10			
FLINT	14	10		28					10	10	27	15	42	15	5	10	10	20	
EPK	8			4	2				5	7.1	4	10	22	5	15	10		15	
ZINC OXIDE		4	4	1							6		10		5				
BENTONITE	1%		2		2						1						2		
ERRO FRITT # 3304					30														
ZIRCOPAX					4													10	
SUPERPAX					8														
ASON'S STAINS COLORS.						25%	50%												
EAD BISILICATE												30							
WOLLASTONITE														5					
TALC														5				5	
DOLOMITE															10				
GROLLEG																	30		
TENN. BALL CLAY																	25		
ALCINED KAOLIN																		15	

HIGH GLOSS

VERY HIGH ALKALIN (SODA).

ADD A PINCH OF BENTONITE + WATER TO MORE THIN MIX.

ADD A PINCH OF CMC POWDER + WATER + MINUS EQUIVALENT

DO NOT USE ANY COPPER COLORANT IN ANY LEAD GLAZE.

VERY OPAQUE AND VERY WHITE BASE.

THIS IS THE SAME GLAZE AS (C) BUT USES MISSIONS $BaCO_3$

BARIUM/04 MATT - BUT THIS ONE IS NON/PASTEUR.

NO FRITTS - RAW MATERIAL GLAZE.