

Staley Red to Green

CHRIS STALEY PORCELAIN

Custer	50
Whiting	15
EPK	13
Dolomite	2
Flint	20
copper carb	8
iron ox.	1
bent	2

GROLLE6	55
CUSTER FELDSPAR	20
FLINT	13
PYROTROL	12
BENT.	3

OR

Rob's Green

Cornwall stone	75
Whiting	18
Colemanite	5
Copper carb	10
Barium carb	10
Bent	2

GROLLE6	25
#6 TILE	25
CUSTER FELDSPAR	20
FLINT	13
PYROTROL	12
BENT	3

Iron Crackle

Barium	800
Whiting	350
Custer	2500
EPK	200
Flint	1200
Copper carb	500
Rutile	100