

Glazes from Oh
Cone 8-9-10

1. Off-white Matte

usterspar	45
whiting	25
epk	24
titanium dioxide	5

2. Oh's Lavender/Pink Matte Glaze

usterspar	40
whiting	10
flint	20
dolomite	30
chrome ox.	2

NOTES: #1 is Oh's nice 'en soft white
breaking to brown glaze.

To get his lavender/pink glaze, he
puts #2 over #1.

Oh get's his tiger colored glaze by
putting #4 over #3. It crawls a bit.

#5 is what Oh put over his inlayed
colored clay pieces.

3. Oh's Brown/Black Glaze

usterspar	74.5
zinc ox.	2.2
dolomite	4.9
whiting	2.7
epk	6.9
flint	8.7
red iron ox	8.0

4. Oh's Opaque White Glaze

usterspar	48.9
epk	25.1
dolomite	22.4
whiting	3.5

5. Oh's Clear Glaze

usterspar	8
whiting	31
barium carb.	3
magnesium carb.	2
epk	34
flint	22